



39.95093, -108.99196, 6026.6ft, 326°  
06/04/2020 10:52:29 AM



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

**Photo 1. Location.**

**Banta Ridge 16-19-1-103     API: 05-103-10311**  
**Inspection: 700401832**



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

**Photo 2. Separator and meter building.**

**Banta Ridge 16-19-1-103     API: 05-103-10311**  
**Inspection: 700401832**





**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources


**Photo 3. Tanks.**

**Banta Ridge 16-19-1-103      API: 05-103-10311**  
**Inspection: 700401832**



Leak fixed

New leak







39.95124, -108.9923, 5994.4ft, 322°  
06/04/2020 10:54:42 AM



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Photo 5. Well head.

Banta Ridge 16-19-1-103      API: 05-103-10311  
Inspection: 700401832