

Inspection Photos
Location Name: Hiawatha State 2-36
Location ID: 313297



Photo 1. Overview of location taken facing east.



Photo 2. Stained soil.



Inspection Photos
Location Name: Hiawatha State 2-36
Location ID: 313297



Photo 3. Stained soil.



Photo 4. Stained soil.



Inspection Photos
Location Name: Hiawatha State 2-36
Location ID: 313297



Photo 5. Incomplete tank labels.



Photo 6. Incomplete tank labels.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources