

Inspection Photos
Location Name: Hubert Morrison A #1
API: 05-067-06899



Spill/Release Point ID #476772.



Wellhead is wet with lubricating oil from stuffing box.

Inspection Photos
Location Name: Hubert Morrison A #1
API: 05-067-06899



Domestic tap at separator.



Release area fenced off with orange safety fencing.

Inspection Photos
Location Name: Hubert Morrison A #1
API: 05-067-06899



Evidence of flow into irrigation channel.



Spill/Release Point ID #476772 with Hubert Morrison A #1 wellhead and production equipment in the background.

Inspection Photos
Location Name: Hubert Morrison A #1
API: 05-067-06899



Outfall of irrigation channel.



Irrigation channel flood irrigating field.