

Inspection Photos
Operator: BP America
API#: 067-08807
Date: 6/3/2020



Photo 1. View of the project area from the well pad entrance facing center.



Photo 2. View of the northern fill slope from the northwestern corner facing eastward. Revegetation is progressing with crested wheatgrass, western wheatgrass, and smooth brome.



Photos 3. View of the eastern project area from the southeastern corner facing northward.



Photo 4. View of reference area comprised of pinyon and juniper woodland with understory of antelope bitterbrush, big sagebrush, James galleta, and penstemon.