

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/08/2020

Submitted Date:

06/08/2020

Document Number:

699101864**FIELD INSPECTION FORM**Loc ID 450479 Inspector Name: Burns, Adam On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 100322Name of Operator: NOBLE ENERGY INCAddress: 1001 NOBLE ENERGY WAYCity: HOUSTON State: TX Zip: 77070**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:9 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		NBL_DJBU_Inspections@NB LENERGY.COM	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
448090	TANK BATTERY	AC	10/19/2016		-	Hanscome C #21-19 448090	SI

General Comment:

LocationOverall Good: ☒

Signs/Marker:			
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: Adequate

Corrective Action:

Date: _____

Overall Good: ☒

Spills:					
Type	Area	Volume			

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Fencing/:			
Type	SEPARATOR		
Comment:	Barbwire		
Corrective Action:		Date:	
Type	OTHER		
Comment:	Barbwire around meter run		
Corrective Action:		Date:	
Type	IGNITOR/COMBUSTOR		
Comment:	Barbwire		
Corrective Action:		Date:	
Type	TANK BATTERY		
Comment:	Wire		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Gas Meter Run	# 3		
Comment:			
Corrective Action:		Date:	
Type: Emission Control Device	# 2		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 4		

Comment:		
Corrective Action:		Date:
Type: Horizontal Heated Separator	# 2	
Comment:		
Corrective Action:		Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	2	300 BBLs	STEEL AST		40.303050,-104.557940
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:					
Corrective Action:					
Date:					
Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	2	OTHER	PBV CONCRETE		,
Comment:	Shares containment with crude oil tanks.				
Corrective Action:					
Corrective Action:					
Date:					

Paint

Condition	
Other (Content)	
Other (Capacity)	60 BBL
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				
Corrective Action:				
Date:				

Venting:

Yes/No	NO
Comment:	
Corrective Action:	
Corrective Action:	
Date:	

Flaring:

Type	
------	--

Comment:			
Corrective Action:		Date:	

Inspected FacilitiesFacility ID: 448090 Type: TANK API Number: - Status: AC Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned

Reminder: _____

Comment: SI

Corrective Action: _____

Date: _____

COGCC Comments

Comment

User

Date

COGCC Inspection Report Summary

On Monday 6/8/20 at approximately 0747hrs, I, Inspector Adam Burns,
 Conducted an on-site inspection at Hanscome C21-19 Tank Battery of Noble Energy at
 Facility ID: 448090 in Weld County, Colorado.

While there, I observed a tank battery that is shut in.

No violation of the COGCC rules were observed at the time of inspection.

This is a summary of inspection report.

Continuing education inspections

burnsa

06/08/2020

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699101865	Inspection Photo	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5168660