

# *Inspection Photos*

*Loc#314169*

*Operator: RMNG/Blk Hills*

*Inspection #:692402270*

*Inspection Date: 5/28/20*



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



Photo#1:  
Overview of Location.

May 28, 2020



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: RMTN NG-BLK Hills Wolf Creek Loc#314169



Photo#2:  
Tracking off Pad into Interim area.



Photo#3:  
Tracking off Pad into BMPs.

May 28, 2020



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: RMTN NG-BLK Hills Wolf Creek Loc#314169



Photo#4:  
Sediment migration is occurring.



Photo#5:  
Sediment migration is occurring.

May 28, 2020



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: RMTN NG-BLK Hills Wolf Creek Loc#314169



Photo#6:  
Material/soil not contained by BMPs.

Photo#7:  
Material/soil not contained by BMPs.

May 28, 2020