

# *Inspection Photos*

*Loc#334844*

*Operator: Caerus*

*Inspection Number: 692402275*

*Inspection Date: 5/26/20*



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



Photo#1:  
Overview of Location.

May 26, 2020



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Caerus Hill Loc#334844





Photo#2:  
Site appears heavily grazed.



Photo#3:  
Scotch thistle, B List Noxious weed has had controls applied..

May 26, 2020