

# *Inspection Photos*

*Loc#335788*

*Operator: Terra*

*Inspection Number: 692402250*

*Inspection Date: 5/27/20*



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



Photo#1:  
Overview of Location.

May 27, 2020



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Terra Federal Loc#335788





Photo#2:  
Undercutting of rocked checks.



Photo#3:  
Interim area.

May 27, 2020