

BP L48 San Juan



V2 Compliance Follow Up Form

18143734024

Reference Number:

Form Name:

Submitter Name:

Submission Date:

Location:

20200529-18143734024

V2 Compliance Follow Up Form

Cole Nichols (colen@horizonenvservices.com) |
colen@horizonenvservices.com

May 29, 2020 9:58:25 AM MDT

91 S Skylane Dr, Durango, CO 81303, USA

May 29, 2020 9:58:19 AM MDT [[View Map](#)]

INFORMATION

Section 1

Name

colen@horizonenvservices.com

Date

May 22, 2020

Well Name

ARCHULETA-DIX GAS UNIT 2

API Number

50670908800

Select State

Colorado

Work type

COGCC Inspection AR

Action Complete

Other

Photo of first corrective action completed



Completed work description Corrective
Action 1

location sign

Photo of second corrective action completed



**Completed work description of corrective
action 2**

treated noxious weeds

Photo of third corrective action completed



**Completed work description of corrective
action 3**

treated noxious weeds

Photo of fourth corrective action completed



Completed work description

treated noxious weeds

Completed work description of corrective action 4

treated noxious weeds

Additional photos

**Completed work description**

treated noxious weeds in reclamation area and on pad

Summary of all work completed

previous treatment dates 7/18/16, 7/17/17, 6/7/18, 6/24/19