

BP L48 San Juan



## V2 Compliance Follow Up Form

18143729847

**Reference Number:**

**Form Name:**

**Submitter Name:**

**Submission Date:**

**Location:**

20200529-18143729847

V2 Compliance Follow Up Form

Cole Nichols (colen@horizonenvservices.com) |  
colen@horizonenvservices.com

May 29, 2020 10:02:07 AM MDT

557 Airpark Dr, Durango, CO 81303, USA

May 29, 2020 10:01:14 AM MDT [ [View Map](#) ]

## INFORMATION

### Section 1

<b>Name</b>	colen@horizonenvservices.com
<b>Date</b>	May 22, 2020
<b>Well Name</b>	ARCHULETA-DIX GAS UNIT 1
<b>API Number</b>	50670703800
<b>Select State</b>	Colorado
<b>Work type</b>	COGCC Inspection AR
<b>Action Complete</b>	Other
<b>Photo of first corrective action completed</b>	



Completed work description Corrective  
Action 1

location sign

Photo of second corrective action completed





**Completed work description of corrective  
action 2**

treated noxious weeds

**Photo of third corrective action completed**





**Completed work description of corrective  
action 3**

treated noxious weeds

**Photo of fourth corrective action completed**



**Completed work description**

treated noxious weeds

**Completed work description of corrective action 4**

treated noxious weeds

**Additional photos**



**Completed work description**

treated noxious weeds in reclamation area and on pad

**Summary of all work completed**

previous treatment dates 7/18/16, 7/17/17, 6/7/18, 6/24/19