

BP L48 San Juan



V2 Compliance Follow Up Form

18143801537

Reference Number:

Form Name:

Submitter Name:

Submission Date:

Location:

20200529-18143801537

V2 Compliance Follow Up Form

Kenneth Canterbury (kenneth.canterbury@crossfire-llc.com) | kenneth.canterbury@crossfire-llc.com

May 29, 2020 2:29:21 PM MDT

5308 Co Rd 302, Durango, CO 81303, USA

May 29, 2020 2:28:35 PM MDT [[View Map](#)]

INFORMATION

Section 1

Name	kenneth.canterbury@crossfire-llc.com
Date	Apr 30, 2020
Well Name	JOHNSON, VK GAS UNIT A 2
API Number	50670867300
Select State	Colorado
Work type	COGCC Inspection AR
Action Complete	Compliance Inspection Actions Grading of Road Grading of Well Pad
Photo of first corrective action completed	



Completed work description Corrective
Action 1

Compliance

Photo of second corrective action completed



**Completed work description of corrective
action 2**

Graded location

Photo of third corrective action completed



Completed work description of corrective action 3

Hauled gravel on access road

Photo of fourth corrective action completed



Completed work description

Cleaned up location

Completed work description of corrective action 4

Cleaned up location

Summary of all work completed

Compliance, graded location, hauled gravel on access road and cleaned up location