

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/14/2020

Submitted Date:

06/09/2020

Document Number:

700300012**FIELD INSPECTION FORM**Loc ID 326297 Inspector Name: LABOWSKIE, STEVE On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 10133Name of Operator: HILCORP ENERGY COMPANYAddress: P O BOX 61229City: HOUSTON State: TX Zip: 77208**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**7 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Shorty, Priscilla		pshorty@hilcorp.com	<a href="#">All SW Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
216188	WELL	PR	03/16/1993	GW	067-07794	HUBER-LEWIS 2-33	PR
455098	GAS COMPRESSO R STATION	AC	05/23/2018		-	HUBER-LEWIS 02-33 FC - CDP	AC

**General Comment:**

**Location**Overall Good: ☒**Signs/Marker:**

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

**Emergency Contact Number:**

Comment:		
Corrective Action:		Date: _____

**Good Housekeeping:**

Type	DEBRIS		
Comment:	a few pieces of small trash and debris off edge of pad on rec area		
Corrective Action:		Date:	

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Fencing/:**

Type	OTHER		
Comment:	metal sound walls around compressor		
Corrective Action:		Date:	
Type	TANK BATTERY		
Comment:	post and wire around opoen top below grade tank		
Corrective Action:		Date:	

**Equipment:**

Type: Flow Line	# 1		corrective date
Comment:	2" to separator		
Corrective Action:		Date:	

**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**Facility ID: 216188 Type: WELL API Number: 067-07794 Status: PR Insp. Status: PR**Complaint**

Comment: Sound survey conducted in response to complaint doc#200448922 from landowner to east/northeast in additon to complaint doc#200448925 concerning low frequency noise from landowner due east. Low nfrequency noise readings (c-scale) were also taken at each residence directly after obtaining sound readings at location for a-scale. See attachemnt page for link to sound surveys. A-scale at 350' 40 (db)a in direction of Zollinger residence and 41.6 db(a) in dorection of Casey residence which was slightly higher in in elevation at 350'. C-scale surveys were 52.8 and 53.2 db(c) respectively. 300' and 100' survey points were used and extrapolated to the compliance point of 350'.

Corrective Action:

Date:

Facility ID: 455098 Type: GAS API Number: - Status: AC Insp. Status: AC**Complaint**

Comment:

Corrective Action:

Date:

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass					
Gravel	Pass	Compaction	Pass	Material Handling And Spill Prevention		spill prevention on lube tank

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
700300036	Casey a-scale	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5169923">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5169923</a>
700300037	Casey c-scale at residence	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5169924">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5169924</a>
700300038	Zollinger a-scale	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5169925">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5169925</a>
700300039	Zollinger c-scale	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5169926">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5169926</a>