

Inspection Photos
Operator: BP America
API#: 067-06949
Date: 6/8/2020



Photo 1. View of the project area from the well pad entrance facing center.



Photo 2. View of the eastern fill slope from the northeastern corner facing southward. Revegetation is progressing with grasses such as western wheatgrass and smooth brome.



Photo 3. View of the southern project area from the southwestern corner facing eastward.



Photo 4. View of reference area comprised of ponderosa pine woodland with understory of gambel oak, and grasses/forbs such as muttongrass, western wheatgrass, and milkvetch.