

Final Reclamation Inspection

June 2, 2020

Operator: TOP OPERATING COMPANY - 39560

API: 05-123-08139

Inspection Document #: 697501600

Weld County, CO

NENE Section 25 T2N R67W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: SCHNEIDER #1
API: 05-123-08139



Photo 1. Photo taken from the eastern battery location, facing East. Photo illustrates all oil and gas equipment has been removed from location.

Inspection Photos
Location Name: SCHNEIDER #1
API: 05-123-08139



Photo 2. Photo taken from the eastern battery location, facing South. Photo illustrates the battery location appears to be a staging area for gravel mining operations which is also part of a land use change (City of Aurora). No vegetative growth was observed at the battery location.

Inspection Photos
Location Name: SCHNEIDER #1
API: 05-123-08139



Photo 3. Photo taken from the eastern battery location, facing West. See comments under Photo 2.

Inspection Photos
Location Name: SCHNEIDER #1
API: 05-123-08139



Photo 4. Photo taken from the southern battery location, facing South. Photo illustrates the well location and well location access road no longer exist, as it as been mined for gravel.