

Inspection Photos
Location Name: Mumby State 36H-P266 TB
Location ID: 319537




Photo 1 TB/Signs

Photo 2 TB

Inspection Photos
Location Name: Mumby State 36H-P266 TB
Location ID: 319537



Colorado Oil & Gas Conservation Commission
 6495 Co Rd 37, Fort Lupton, CO 80621, USA
 40.09071, -104.71901, 4935.0ft, 201°
 06/09/2020 14:24:03



Colorado Oil & Gas Conservation Commission
 6495 Co Rd 37, Fort Lupton, CO 80621, USA
 40.09065, -104.71906, 4937.0ft, 94°
 06/09/2020 14:24:21

Photo 3 Gas Meter Run

Photo 4 card inside meter house

Inspection Photos
Location Name: Mumby State 36H-P266 TB
Location ID: 319537



Photo 5 Horizontal Heated Separators

Photo 6 ECDs

Inspection Photos
Location Name: Mumby State 36H-P266 TB
Location ID: 319537



Photo 7 VRU

Photo 8 Trash outside fence of tank battery

Inspection Photos
Location Name: Mumby State 36H-P266 TB
Location ID: 319537




Photo 9 Box of trash inside of metal berm

Photo 10 unused valve inside of metal berm

Inspection Photos
Location Name: Mumby State 36H-P266 TB
Location ID: 319537



Colorado Oil & Gas Conservation Commission
5033 Co Rd 37, Fort Lupton, CO 80621, USA
40-09027 - 104 71787 - 49522B - 318
06/09/2020 14:40:01

Photo 11 unused pipe parts inside of metal berm