

Inspection Photos

API: 05-055-06309

Operator: ALTA MESA SERVICES

Inspection Date: 6/10/2020



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-055-06309 | Date: 6/10/2020

Inspection Photos



Photo 1. Facing north toward the access road which has not been recontoured and reclaimed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-055-06309 | Date: 6/10/2020

Inspection Photos



Photo 2. The cattleguad and gates remain at the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-055-06309 | Date: 6/10/2020

Inspection Photos



Photo 3. Facing southwest toward the cut slope and portion of the location which has not been reclaimed. There are numerous noxious weeds growing throughout the location shown by red arrow which points to Scotch thistle List B noxious weed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-055-06309 | Date: 6/10/2020

Inspection Photos



Photo 4. Facing northeast toward the location which has not been reclaimed. There are numerous noxious weeds growing throughout the location shown by red arrow which points to Scotch thistle List B noxious weed. Other weeds observed were Cheat grass, Russian thistle, among other weeds.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-055-06309 | Date: 6/10/2020

Inspection Photos



Photo 5. There is a dead tree and fabric debris left on location where trees were transplanted.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-055-06309 | Date: 6/10/2020

Inspection Photos



Photo 6. There are trees that have died which were planted at the location. The dead tree debris need to be removed and new trees replanted.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-055-06309 | Date: 6/10/2020

Inspection Photos



Photo 7. View of ground cover at western side of the location which is composed of undesirable and noxious weed growth which was observed throughout the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-055-06309 | Date: 6/10/2020

Inspection Photos



Photo 8. Facing northeast at the west side of the location. There are numerous noxious weeds growing throughout the location shown by red arrow which points to Scotch thistle List B noxious weed. Other weeds observed were Cheat grass, Russian thistle, among other weeds.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-055-06309 | Date: 6/10/2020

Inspection Photos



Photo 9. Facing southeast standing at the northwest portion of the location. There is weed debris throughout the location which needs to be removed and weed control must be performed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-055-06309 | Date: 6/10/2020

Inspection Photos



Photo 10. The weed debris (Russian thistle) is collecting along the perimeter fence. This debris needs to be removed and controlled from spreading onto adjacent undisturbed land.



Inspection Photos



Photo 11. Facing south at the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-055-06309 | Date: 6/10/2020

Inspection Photos



Photo 12. East side of the location facing southwest. This area of the location has not been recontoured and reclaimed and gravel remains within this area.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-055-06309 | Date: 6/10/2020

Inspection Photos



Photo 13. Facing south along the fill slope of the location. This area of the location has not been recontoured and reclaimed and gravel remains within this area.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-055-06309 | Date: 6/10/2020

Inspection Photos



Photo 14. Facing west toward the surrounding undisturbed reference area which is composed of Native Blue grama grassland and Pinion, Juniper woodland.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-055-06309 | Date: 6/10/2020