

Inspection Photos
Location Name: LORENCITO 13-17
API#: 05-071-07981
INSP. #: 695102883



PHOTO 1: LOCATION



PHOTO 2: WELL SIGN



Inspection Photos
Location Name: LORENCITO 13-17
API#: 05-071-07981
INSP. #: 695102883

Inspection Report

Collection Line: 107107981
 Location: LORENCITO 13-17-34-65
 System: 1000000000
 Field: 1000000000
 State: 1000000000
 Production: 1000000000
 Purchase: 1000000000

Current Plate Size: 8.575
 Pipe Size: 2.000
 Alarms: Pressure
 Pressure Base: 14.7

Tap Type: SP Tap Location
 Temperature Bias: 0
 Temperature Base: 60

Flange: Up Stream
 Specific Gravity: 1.000

Plate Inspected? Yes No
 Edges Sharp? Yes No
 Seal Ring Damaged? Yes No
 Tube Inspected? Yes No
 Dirty? Yes No
 Nipped? Yes No
 Warped? Yes No
 Bevel Downstream? Yes No

FLOW TEST RESULTS				PRESSURE				TEMPERATURE			
Flow	Pressure	Temperature	Time	Flow	Pressure	Temperature	Time	Flow	Pressure	Temperature	Time
100.00	100.00	100.00	100.00	111.28	111.28	111.28	111.28	111.28	111.28	111.28	111.28
75.00	75.00	75.00	75.00	111.28	111.28	111.28	111.28	111.28	111.28	111.28	111.28
50.00	50.00	50.00	50.00	111.28	111.28	111.28	111.28	111.28	111.28	111.28	111.28
25.00	25.00	25.00	25.00	111.28	111.28	111.28	111.28	111.28	111.28	111.28	111.28

Calibrated By: Mark Summers
 Date: 2020/06/03 10:06:53



PHOTO 3: GAS METER CAL. REPORT.

PHOTO 4: UNUSED EQUIPMENT STORED ON LOCATION.
REMOVE UNUSED EQUIPMENT COMPLY WITH RULE 603.f.
CA DATE 9-3-20.

Inspection Photos
Location Name: LORENCITO 13-17
API#: 05-071-07981
INSP. #: 695102883



PHOTO 5: UNUSED EQUIPMENT (TWO UNUSED 2" RISERS & ONE 1" RISER). REMOVE UNUSED EQUIPMENT COMPLY WITH NTO AND RULE 603.F. CA DATE 9-3-20.