

Inspection Photos
Operator: BP America
API#: 067-08656
Date: 6/8/2020



Photo 1. View of the project area from the well pad entrance facing center.



Photo 2. View of the eastern fill slope from the southeastern corner facing northward. Revegetation is progressing with western wheatgrass and rubber rabbitbrush.



Photo 3. View of the eastern fill slope from the southeastern corner facing northward. Revegetation is progressing with western wheatgrass and rubber rabbitbrush.



Photo 4. View of reference area comprised of ponderosa pine woodland with understory of gambel oak, and grasses/forbs such as sandberg bluegrass, western wheatgrass, and penstemon.