

Inspection Photos

6/9/2020

Operator: CAERUS PICEANCE LLC - 10456

Location ID: 439135

Garfield County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

Inspection Photos
Operator Name: CAERUS PICEANCE LLC - 10456
Location ID: 439135



Photo 1: Photo taken from the tank battery, facing west. Photo shows unused equipment (rock-socks) remain stored on the Location.



Photo 2: Photo taken from the east end of the Location, facing southeast. Photo shows various unused equipment/trash debris stored on Location.