

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/10/2020

Submitted Date:

06/10/2020

Document Number:

700700853

**FIELD INSPECTION FORM**Loc ID 334639 Inspector Name: Ramsey, Scott On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

OGCC Operator Number: 10456

Name of Operator: CAERUS PICEANCE LLC

Address: 1001 17TH STREET #1600

City: DENVER State: CO Zip: 80202

**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

10 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name | Phone | Email                                     | Comment |
|--------------|-------|---|---------|
| , Caerus     |       | COGCC.inspections@caerus<br>oilandgas.com |         |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name                | Insp Status |
|-------------|------|--------|-------------|------------|-----------|------------------------------|-------------|
| 211454      | WELL | PR     | 05/14/2005  | GW         | 045-07214 | SAVAGE 1-21                  | PR          |
| 211455      | WELL | PR     | 04/20/2005  | GW         | 045-07215 | SAVAGE 1-11                  | PR          |
| 259442      | WELL | PR     | 10/16/2003  | GW         | 045-07728 | SAVAGE 2-14                  | PR          |
| 259443      | WELL | PR     | 10/16/2003  | GW         | 045-07729 | SAVAGE 2-34                  | PR          |
| 259475      | WELL | PR     | 04/20/2005  | GW         | 045-07733 | SAVAGE 2-24                  | PR          |
| 277782      | WELL | PR     | 08/21/2005  | GW         | 045-10782 | SAVAGE FEDERAL 2-1D<br>(RE1) | PR          |

**General Comment:****COGCC Inspection Report Summary**

On Wednesday 6/10/20 at approximately 12:30 PM, I, Inspector Scott Ramsey, conducted a follow up inspection at Caerus RE1, at Location # 334639 in Garfield Colorado.

While there, I observed normal production operations. All C/A(s) from previous inspection document # 694900296 have been completed.

This is a summary of inspection report.

**Location****Lease Road:**

|                    |        |       |  |
|--------------------|--------|-------|--|
| Type               | Access |       |  |
| comment:           |        |       |  |
| Corrective Action: |        | Date: |  |

Overall Good: ☒**Signs/Marker:**

|                    |                      |       |  |
|--------------------|----------------------|-------|--|
| Type               | CONTAINERS           |       |  |
| Comment:           |                      |       |  |
| Corrective Action: |                      | Date: |  |
| Type               | WELLHEAD             |       |  |
| Comment:           |                      |       |  |
| Corrective Action: |                      | Date: |  |
| Type               | BATTERY              |       |  |
| Comment:           |                      |       |  |
| Corrective Action: |                      | Date: |  |
| Type               | TANK LABELS/PLACARDS |       |  |
| Comment:           |                      |       |  |
| Corrective Action: |                      | Date: |  |

Emergency Contact Number:

|                    |     |             |
|--------------------|-----|-------------|
| Comment:           | 911 |             |
| Corrective Action: |     | Date: _____ |

**Good Housekeeping:**

|                    |        |       |  |
|--------------------|--------|-------|--|
| Type               | DEBRIS |       |  |
| Comment:           |        |       |  |
| Corrective Action: |        | Date: |  |

Overall Good: ☒**Spills:**

|      |      |        |  |  |
|------|------|--------|--|--|
| Type | Area | Volume |  |  |
|------|------|--------|--|--|

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Fencing/:**

|                    |           |       |  |
|--------------------|-----------|-------|--|
| Type               | SEPARATOR |       |  |
| Comment:           |           |       |  |
| Corrective Action: |           | Date: |  |
| Type               | WELLHEAD  |       |  |
| Comment:           |           |       |  |
| Corrective Action: |           | Date: |  |

|                                   |  |  |                 |
|-----------------------------------|--|--|-----------------|
| <b>Equipment:</b>                 |  |  | corrective date |
| Type: Vertical Heated Separator   | # 4  |  |                 |
| Comment:                          |  |  |                 |
| Corrective Action:                |  |  | Date:           |
| Type: Bird Protectors             | # 3  |  |                 |
| Comment:                          |  |  |                 |
| Corrective Action:                |  |  | Date:           |
| Type: Plunger Lift                | # 6  |  |                 |
| Comment:                          |  |  |                 |
| Corrective Action:                |  |  | Date:           |
| Type: Gas Meter Run               | # 1  |  |                 |
| Comment:                          |  |  |                 |
| Corrective Action:                |  |  | Date:           |
| Type: Ancillary equipment         | # 1  |  |                 |
| Comment:                          | 500 gallon methanol tank next to meter house |  |                 |
| Corrective Action:                |  |  | Date:           |
| Type: Horizontal Heated Separator | # 2  |  |                 |
| Comment:                          |  |  |                 |
| Corrective Action:                |  |  | Date:           |

**Tanks and Berms:**

|                    |  |          |           |         |        |       |
|--------------------|--|----------|-----------|---------|--------|-------|
| Contents           | #  | Capacity | Type      | Tank ID | SE GPS |       |
| METHANOL           | 1  | 1000 GAL | STEEL AST |         | ,      |       |
| Comment:           | shared containment with condensate tanks |          |           |         |        |       |
| Corrective Action: |  |          |           |         |        | Date: |

**Paint**

|                  |          |  |
|------------------|----------|--|
| Condition        | Adequate |  |
| Other (Content)  |          |  |
| Other (Capacity) |          |  |
| Other (Type)     |          |  |

**Berms**

|                    |          |                     |                     |             |        |  |
|--------------------|----------|---------------------|---------------------|-------------|--------|--|
| Type               | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |        |  |
|                    |          |                     |                     |             |        |  |
| Comment:           |          |                     |                     |             |        |  |
| Corrective Action: |          |                     |                     |             | Date:  |  |
| Contents           | #        | Capacity            | Type                | Tank ID     | SE GPS |  |
| CONDENSATE         | 3        | 300 BBLS            | STEEL AST           |             | ,      |  |
| Comment:           |          |                     |                     |             |        |  |
| Corrective Action: |          |                     |                     |             |        |  |

**Paint**

|           |          |  |
|-----------|----------|--|
| Condition | Adequate |  |
|-----------|----------|--|

Inspector Name: Ramsey, Scott

|                  |  |
|------------------|--|
| Other (Content)  |  |
| Other (Capacity) |  |
| Other (Type)     |  |

**Berms**

|                    |          |                     |                     |             |       |
|--------------------|----------|---------------------|---------------------|-------------|-------|
| Type               | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |       |
| Metal              | Adequate | Walls Sufficient    | Base Sufficient     | Adequate    |       |
| Comment:           |          |                     |                     |             |       |
| Corrective Action: |          |                     |                     |             | Date: |

**Venting:**

|                    |    |  |       |
|--------------------|----|--|-------|
| Yes/No             | NO |  |       |
| Comment:           |    |  |       |
| Corrective Action: |    |  | Date: |

**Flaring:**

|                    |  |  |       |
|--------------------|--|--|-------|
| Type               |  |  |       |
| Comment:           |  |  |       |
| Corrective Action: |  |  | Date: |

| Inspected Facilities  |           |       |      |             |           |         |    |               |    |
|-----------------------|-----------|-------|------|-------------|-----------|---------|----|---------------|----|
| Facility ID:          | 211454    | Type: | WELL | API Number: | 045-07214 | Status: | PR | Insp. Status: | PR |
| <b>Producing Well</b> |           |       |      |             |           |         |    |               |    |
| Comment:              | producing |       |      |             |           |         |    |               |    |
| Corrective Action:    |           |       |      |             |           | Date:   |    |               |    |
| Facility ID:          | 211455    | Type: | WELL | API Number: | 045-07215 | Status: | PR | Insp. Status: | PR |
| <b>Producing Well</b> |           |       |      |             |           |         |    |               |    |
| Comment:              | producing |       |      |             |           |         |    |               |    |
| Corrective Action:    |           |       |      |             |           | Date:   |    |               |    |
| Facility ID:          | 259442    | Type: | WELL | API Number: | 045-07728 | Status: | PR | Insp. Status: | PR |
| <b>Producing Well</b> |           |       |      |             |           |         |    |               |    |
| Comment:              | producing |       |      |             |           |         |    |               |    |
| Corrective Action:    |           |       |      |             |           | Date:   |    |               |    |
| Facility ID:          | 259443    | Type: | WELL | API Number: | 045-07729 | Status: | PR | Insp. Status: | PR |
| <b>Producing Well</b> |           |       |      |             |           |         |    |               |    |
| Comment:              | producing |       |      |             |           |         |    |               |    |
| Corrective Action:    |           |       |      |             |           | Date:   |    |               |    |
| Facility ID:          | 259475    | Type: | WELL | API Number: | 045-07733 | Status: | PR | Insp. Status: | PR |
| <b>Producing Well</b> |           |       |      |             |           |         |    |               |    |
| Comment:              | producing |       |      |             |           |         |    |               |    |
| Corrective Action:    |           |       |      |             |           | Date:   |    |               |    |
| Facility ID:          | 277782    | Type: | WELL | API Number: | 045-10782 | Status: | PR | Insp. Status: | PR |
| <b>Producing Well</b> |           |       |      |             |           |         |    |               |    |
| Comment:              | producing |       |      |             |           |         |    |               |    |
| Corrective Action:    |           |       |      |             |           | Date:   |    |               |    |

**Reclamation - Storm Water - Pit****Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Berms            |                 | Check Dams              |                       |               |                          |         |
| Ditches          |                 | Culverts                |                       |               |                          |         |
| Gravel           |                 | Ditches                 |                       |               |                          |         |
|                  |                 | Gravel                  |                       |               |                          |         |

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description    | URL   |
|--------------|----------------|---|
| 700700859    | photos for RE1 | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5171325">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5171325</a> |