

Inspection Photos

API: 05-055-06017

Operator: OXY USA INC

Inspection Date: 6/9/2020



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 05-055-06017 | Date: 6/9/2020

Inspection Photos



Photo 1. Facing northeast along the main road. Rock checkdamns have been repaired since previous inspection. Lat/Long:37.69860,-105.21673



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-055-06017 | Date: 6/9/2020

Inspection Photos



Photo 2. Facing southeast toward the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-055-06017 | Date: 6/9/2020