

Inspection Photos

6/9/2020

Operator: CAERUS PICEANCE LLC # 10456#
10091

Location ID: 335997

Garfield County, CO

Aaron Trujillo
NW Reclamation Specialist
COGCC

Inspection Photos

Operator Name: CAERUS PICEANCE LLC # 10456# 10091

Location ID: 335997



Photo 1: Photo taken from southeast end of the Location, facing southwest. Photos 1-4 provide an overview of the Location from southwest, west, northwest to northeast. Photos show interim reclamation activities appear to have been conducted and is “in process”.



Photo 2: See comments under photo 1.

Inspection Photos

Operator Name: CAERUS PICEANCE LLC # 10456# 10091

Location ID: 335997



Photo 3: See comments under photo 1.



Photo 4: See comments under photo 1.

Inspection Photos
Operator Name: CAERUS PICEANCE LLC # 10456# 10091
Location ID: 335997



Photo 5: Photo of the two active wells on the Location.



Photo 6: Photo taken from the northeast end of the Location. Photo shows unused equipment/trash debris stored on the Location.

Inspection Photos

Operator Name: CAERUS PICEANCE LLC # 10456# 10091

Location ID: 335997



Photo 7: Photo taken from the northeast end of the Location. Photo shows unused equipment (rock-socks) stored on the Location.



Photo 8: Photo taken from the south end of the Location. Photo shows unused equipment/materials stored on the Location.



Inspection Photos

Operator Name: CAERUS PICEANCE LLC # 10456# 10091

Location ID: 335997



Photo 9: Photo taken from the south end of the Location. Photo shows unused equipment stored on the Location.

