

Inspection Photos

Location Name: NATIONAL HOG FARM-65N63W /17SENW

Location #: 331004



Photo #1

National Hog Farm 17-22 (05-123-20015) Wellsite

Plugged & Abandoned | PA

~ 20 yds.

Reclamation progressing



Photo #2

National Hog Farm 17-22, 17-21 Battery site

Abandoned: ALL equipment removed

Reclamation progressing

Inspection Photos

Location Name: NATIONAL HOG FARM-65N63W /17SENW

Location #: 331004



Photo #3

National Hog Farm 17-22, 17-21 Battery site

Abandoned: *Most equipment removed*

Unused Equipment: *Gas meter run & riser*

Reclamation progressing

prior insp.



Photo #4

National Hog Farm 17-22, 17-21 Battery site

Abandoned: *ALL equipment removed*

Reclamation progressing

Inspection Photos

Location Name: NATIONAL HOG FARM-65N63W /17SENW

Location #: 331004



Colorado Oil & Gas Conservation Commission
40.40124, -104.4635, 1406.0m, 349°
12/30/2019 02:58:13 PM

Photo #5

National Hog Farm 17-22, 17-21 Battery site

Abandoned: *Most equipment removed*

Unused Equipment: *Gas meter run & riser*

Reclamation progressing

prior insp.



Colorado Oil & Gas Conservation Commission
40.40124, -104.46353, 4619.3ft, 335°
06/10/2020 14:01:56

Photo #6

National Hog Farm 17-22, 17-21 Battery site

Abandoned: *ALL equipment removed*

Reclamation progressing