

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/04/2020

Submitted Date:

06/04/2020

Document Number:

689704816

FIELD INSPECTION FORM
 Loc ID: 334768
 Inspector Name: LONGWORTH, MIKE
 On-Site Inspection: ☐
 2A Doc Num:
Operator Information:

OGCC Operator Number: 96850

Name of Operator: TEP ROCKY MOUNTAIN LLC

Address: PO BOX 370

City: PARACHUTE State: CO Zip: 81635

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

19 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Inspection, Terra TEP	970-285-9377	COGCCInspectionReports@terraep.com	
Kellerby, Shaun		shaun.kellerby@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
288189	WELL	PR	12/05/2006	GW	045-13171	HOAGLUND PA 331-2	PR
288313	WELL	PR	08/20/2007	GW	045-13215	HOAGLUND PA 341-2	PR
288314	WELL	PR	08/20/2007	GW	045-13214	HOAGLUND PA 41-2	PR
288315	WELL	PR	12/11/2006	GW	045-13213	HOAGLUND PA 31-2	PR
288316	WELL	PR	12/11/2006	GW	045-13212	HOAGLUND PA 431-2	PR
288317	WELL	PR	08/20/2007	GW	045-13211	HOAGLUND PA 441-2	PR
288318	WELL	PR	12/11/2006	GW	045-13210	HOAGLUND PA 531-2	PR
288319	WELL	PR	08/20/2007	GW	045-13209	HOAGLUND PA 541-2	PR
288320	WELL	PR	12/11/2006	GW	045-13208	HOAGLUND PA 342-2	PR
288321	WELL	PR	08/20/2007	GW	045-13207	HOAGLUND PA 42-2	PR
288322	WELL	PR	12/11/2006	GW	045-13206	HOAGLUND PA 332-2	PR
288323	WELL	PR	12/11/2006	GW	045-13205	HOAGLUND PA 32-2	PR
288324	WELL	PR	08/21/2007	GW	045-13204	HOAGLUND PA 542-2	PR
288325	WELL	PR	08/20/2007	GW	045-13203	HOAGLUND PA 532-2	PR
288326	WELL	PR	08/20/2007	GW	045-13202	HOAGLUND PA 432-2	PR
288327	WELL	PR	08/20/2007	GW	045-13201	HOAGLUND PA 442-2	PR

General Comment:

Inspector Name: LONGWORTH, MIKE

I, Inspector Mike Longworth, conducted an inspection on site.

During this inspection the following possible compliance issues were observed:

Tank capacities too small to read at distance.

Install sign to comply with Rule 210.d.

C.A. Date 09/05/2020

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

Location

Lease Road:			
Type	Access		
comment:			
Corrective Action	L	Date:	

Overall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Tank capacity too small to read at distance.		
Corrective Action:	Install sign to comply with Rule 210.d.	Date:	09/05/2020

Emergency Contact Number:

Comment: 911

Corrective Action:

Date: _____

Overall Good: ☐

Spills:				
Type	Area	Volume		

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Fencing/:			
Type	SEPARATOR		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	TANK BATTERY		
Comment:			
Corrective Action:		Date:	

Equipment:			corrective date
Type: Horizontal Heated Separator	# 16		
Comment:			
Corrective Action:		Date:	

Type: Plunger Lift	# 16		
Comment:			
Corrective Action:			Date:
Type: Bird Protectors	# 8		
Comment:			
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
CONDENSATE	1	300 BBLs	STEEL AST		,	
Comment:						
Corrective Action:						Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1	200 BBLs	STEEL AST		,	
Comment:						
Corrective Action:						Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				

Venting:

Yes/No	NO	
Comment:		
Corrective Action:		

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	288189	Type:	WELL	API Number:	045-13171	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	288313	Type:	WELL	API Number:	045-13215	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	288314	Type:	WELL	API Number:	045-13214	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	288315	Type:	WELL	API Number:	045-13213	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	288316	Type:	WELL	API Number:	045-13212	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	288317	Type:	WELL	API Number:	045-13211	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	288318	Type:	WELL	API Number:	045-13210	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	288319	Type:	WELL	API Number:	045-13209	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:						Date:			

Facility ID:	288320	Type:	WELL	API Number:	045-13208	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	288321	Type:	WELL	API Number:	045-13207	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	288322	Type:	WELL	API Number:	045-13206	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	288323	Type:	WELL	API Number:	045-13205	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	288324	Type:	WELL	API Number:	045-13204	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	288325	Type:	WELL	API Number:	045-13203	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	288326	Type:	WELL	API Number:	045-13202	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	288327	Type:	WELL	API Number:	045-13201	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	Producing well								
Corrective Action:						Date:			

--

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass					
		Ditches	Pass			
		Gravel	Pass			
Ditches	Pass					
Gravel	Pass					
		Compaction	Pass			

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402413897	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5167059
689704817	Inspection 689704816 photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5167056