

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/08/2020

Submitted Date:

06/08/2020

Document Number:

701000820

FIELD INSPECTION FORM

Loc ID 303377 Inspector Name: Welsh, Brian On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 97120
Name of Operator: WISE* WAYNE L
Address: P O BOX 5116
City: ENGLEWOOD State: CO Zip: 80155

Findings:

8 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Wise, Wayne	(405) 826-7013	wwise@peakviewenergy.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
253011	WELL	PR	08/11/2003	GW	125-06888	ALICE WELP 1-10	PR

General Comment:

[Routine Inspection](#)

Location			
Lease Road:			
	Type	Access	
	comment:	Trail through pasture	
	Corrective Action:		Date:
Overall Good: <input checked="" type="checkbox"/>			
Signs/Marker:			
	Type	WELLHEAD	
	Comment:	Lease sign mounted to fence at wellhead	
	Corrective Action:		Date:
Emergency Contact Number:			
	Comment:	<input style="width: 100%;" type="text"/>	
	Corrective Action:	<input style="width: 100%;" type="text"/>	
Date: _____			
Overall Good: <input checked="" type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
	Comment:	<input style="width: 100%;" type="text"/>	
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
	Type	WELLHEAD	
	Comment:	Wire panels around wellhead	
	Corrective Action:		Date:
Equipment:			
Type: Vertical Separator	# 1		corrective date
	Comment:	Vertical gas separator 50% buried by meter shed	
	Corrective Action:		Date:
Type: Gas Meter Run	# 1		
	Comment:	Meter run is 1245' southwest of wellhead next to Allison 1-9 meter shed	
	Corrective Action:		Date:
Venting:			
Yes/No			
Comment:			
Corrective Action:			Date:
Flaring:			
Type			
Comment:			
Corrective Action:			Date:

Inspected Facilities

Facility ID: 253011 Type: WELL API Number: 125-06888 Status: PR Insp. Status: PR

Producing Well

Comment: [Producing. Casing production. Central meter run for Allison 9-1 and Welp 1-10 1245' SW of wellhead on NW corner of CR 28 & X](#)

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Other	Pass	Other	Pass			

Comment: [Location and access are grassed over](#)

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT