

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/08/2020

Submitted Date:

06/08/2020

Document Number:

701000821**FIELD INSPECTION FORM**Loc ID 303317 Inspector Name: Welsh, Brian On-Site Inspection ☐ 2A Doc Num: **Operator Information:**OGCC Operator Number: 69760Name of Operator: PETRON DEVELOPMENT COMPANYAddress: 1899 W LITTLETON BLVDCity: LITTLETON State: CO Zip: 80120**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:9 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Walker, Jimmy	(303) 794-5300	jim@petron.net	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
252900	WELL	PR	05/14/1990	GW	125-06776	ALLISON 9-1	PR

General Comment:Routine Inspection

Location

Lease Road:			
Type	Access		
comment:	Trail through farm ground		
Corrective Action		Date:	

Overall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:	Lease sign by HGS		
Corrective Action:		Date:	
Type	OTHER		
Comment:	Lease sign mounted to meter shed		
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:			
Corrective Action:			
	Date:		

Overall Good: ☒

Spills:				
Type	Area	Volume		

In Containment: No

Comment: ☐ Multiple Spills and Releases?

Equipment:			corrective date
Type: Gas Meter Run	# 1		
Comment:	Shared meter run for Allison 9-1 and Welp 1-10 1220' SE @ CR 28 & X		
Corrective Action:		Date:	
Type: Horizontal Separator	# 1		
Comment:	HGS next to wellhead		
Corrective Action:		Date:	
Type: Vertical Separator	# 1		
Comment:	Vertical gas separator 50% buried by meter shed		
Corrective Action:		Date:	

Venting:			
Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:		
Type		
Comment:		

Corrective Action:		Date:	
--------------------	--	-------	--

Inspected Facilities									
Facility ID:	252900	Type:	WELL	API Number:	125-06776	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing. Casing production. Central meter run for Allison 9-1 and Welp 1-10 1220' SE of wellhead on NW corner of CR 28 & X								
Corrective Action:								Date:	

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Other	Pass	Other	Pass			

Comment: Location and access are farmed over

Corrective Action:

Date: _____

Pits: ☐ NO SURFACE INDICATION OF PITType: EvaporationLined: NO

Pit ID:

Lat: 39.978280Long: -102.414630Reference Point: SE

Other: _____

Length: 20Width: 20**Lining:**

Liner Type:

Liner Condition:

Comment:

Corrective Action

Date:

Fencing:

Fencing Type:

Fencing Condition:

Comment:

Corrective Action

Date:

Netting:

Netting Type:

Netting Condition:

Comment:

Corrective Action

Date:

Anchor Trench Present:

Oil Accumulation: NO2+ feet Freeboard: YES

Comment:

Corrective Action

Date: