

Inspection Photos
Location Name: Schroeder 33-32
Location ID: 313167



Photo 1. Overview of location taken facing northwest.



Photo 2. Annual weeds on location.

Inspection Photos
Location Name: Schroeder 33-32
Location ID: 313167



Photo 3. Example of equipment stored on location.



Photo 4. Example of equipment stored on location.

Inspection Photos
Location Name: Schroeder 33-32
Location ID: 313167



Photo 5. Example of equipment stored on location.



Photo 6. Example of equipment stored on location.

Inspection Photos
Location Name: Schroeder 33-32
Location ID: 313167



Photo 7. Example of equipment stored on location.



Photo 8. Example of equipment stored on location.

Inspection Photos
Location Name: Schroeder 33-32
Location ID: 313167



Photo 9. Unmarked risers on location.



Photo 10. Unmarked risers on location.