

Inspection Photos
Location Name: Anderson 43-29
Location ID: 313194



Photo 1. Overview of location taken facing southwest.



Photo 2. Example of equipment stored on location.

Inspection Photos
Location Name: Anderson 43-29
Location ID: 313194



Photo 3. Example of debris, trash, equipment on location.



Photo 4. Example of debris, trash, equipment stored on location.

Inspection Photos
Location Name: Anderson 43-29
Location ID: 313194



Photo 5. Example of debris, trash, equipment on location.



Photo 6. Example of debris, trash, equipment stored on location.



Inspection Photos
Location Name: Anderson 43-29
Location ID: 313194



Photo 7. Example of debris, trash, equipment on location.



Photo 8. Example of debris, trash, equipment stored on location.



Inspection Photos
Location Name: Anderson 43-29
Location ID: 313194



Photo 9. Example of annual weeds on location.



Photo 10. No wellhead sign, equipment stored on location.