

Inspection Photos
Location Name: Sack G Unit #1
Location ID: 320295



Photo 1 WH




Photo 2 Production equipment. Weeds on location and under separator burner.

Inspection Photos
Location Name: Sack G Unit #1
Location ID: 320295



Colorado Oil and Gas Conservation Commission
 39.9855, -104.96663, 1552.9m
 Jun 12, 2020 09:44:09



Colorado Oil and Gas Conservation Commission
 39.98534, -104.96659, 1553.9m
 Jun 12, 2020 09:45:03

Photo 3 tank paint in disrepair