

Inspection Photos
Location Name: Sack #1
Location ID: 319867



Photo 1 WH stained soil appears to have been removed



**Photo 2 Weeds appear to have been cut after inspection
doc#693501375**

Inspection Photos
Location Name: Sack #1
Location ID: 319867



**Photo 3 Weeds appear to have been cut after inspection
doc#693501375**



**Photo 4 3in line installed from production tank to ECD
Inspection hatch closed.**

