

Issue Report

Groseclose 31-30, 125-07219

Report created on June 11, 2020

Captured: June 3, 2020



Type	Count
Erosion	2

No.	Summary	Type	Created	Status
2	Waddles have been installed around location	Erosion	Jun 11, 2020 at 4:46pm	Open
1	Waddles and netting have been installed	Erosion	Jun 11, 2020 at 4:44pm	Open

Erosion



No.	Summary	Created	Status
2	Waddles have been installed around location	Jun 11, 2020 at 4:46 PM	Open
1	Waddles and netting have been installed	Jun 11, 2020 at 4:44 PM	Open

No. 1 OPEN

Captured: Jun 3, 2020 at 12:18pm

**Type**

Erosion

Lat/Long

39.68646, -102.22246

Summary

Waddles and netting have been installed

Created

Jun 11, 2020 at 4:44pm by Craig Quint

No. 2 OPEN

Captured: Jun 3, 2020 at 12:18pm

**Type**

Erosion

Lat/Long

39.68672, -102.22257

Summary

Waddles have been installed around location

Created

Jun 11, 2020 at 4:46pm by Craig Quint