

Inspection Photos
Location Name: Anderson 31-32
Location ID: 313290



Photo 1. Overview of location taken facing southwest.



Inspection Photos
Location Name: Anderson 31-32
Location ID: 313290



Photo 2. Annual weeds on location.



Photo 3. Example of erosion rills on access road.

