

Inspection Photos
Location Name: Moffat County 24-29
Location ID: 313166



Photo 1. Overview of location taken facing northeast.



Photo 2. Example of erosion rills on access road.

Inspection Photos
Location Name: Moffat County 24-29
Location ID: 313166



Photo 3. Example of erosion rills on access road.



Photo 4. Example of erosion rills on access road.