

Inspection Photos
Operator: BP America
API#: 067-08261
Date: 6/11/2020



Photo 1. View of the project area from the northeastern corner facing center.



Photo 2. View of the eastern fill slope from the northeastern corner facing southward. Revegetation is progressing with western wheatgrass, crested wheatgrass, and rubber rabbitbrush.



Photo 3. View of the northern project area from the northeastern corner facing westward.



Photo 4. View of musk thistles within the project area, approximately 250 individuals observed.



Photo 5. View of reference area comprised of pinyon and juniper woodland with understory of black sage, blue grama, James galleta, and desert trumpets.