

Final Reclamation and Stormwater Inspection

June 2, 2020

Operator: CRESTONE PEAK RESOURCES OPERATING LLC - 10633

Location ID: 333216

Inspection Document #: 697501618

Weld County, CO

NESW Section 2 T2N R67W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: ECHEVERRIA-62N67W
Location ID: 333216



Photo 1. Photo taken from the northeastern location, facing South. Photo illustrates barriers in place to keep traffic off the reclamation area.

Inspection Photos
Location Name: ECHEVERRIA-62N67W
Location ID: 333216



Photo 2. Photo taken from the northeastern location, facing South. Photo illustrates Operator has performed final reclamation activities with the evidence of desirable vegetation.

Inspection Photos
Location Name: ECHEVERRIA-62N67W
Location ID: 333216



Photo 3. Photo taken from the southern location, facing East. See comments under Photo 2.

Inspection Photos
Location Name: ECHEVERRIA-62N67W
Location ID: 333216



Photo 4. Photo taken from the southern location, facing West. See comments under Photo 2.

Inspection Photos
Location Name: ECHEVERRIA-62N67W
Location ID: 333216



Photo 5. Photo taken from the southern location, facing West. Photo illustrates a bare area with no vegetation.

Inspection Photos
Location Name: ECHEVERRIA-62N67W
Location ID: 333216



Photo 6. Photo taken from the northeastern location, facing West. Photo illustrates a bare areas with no vegetation.

Inspection Photos
Location Name: ECHEVERRIA-62N67W
Location ID: 333216



Photo 7. Photo taken from the location. Photo illustrates a List B Colorado noxious weed, Musk thistle. There were no Musk thistles observed with shoots.

Inspection Photos
Location Name: ECHEVERRIA-62N67W
Location ID: 333216



Photo 8. Photo taken from the adjacent well (123-19708), facing West. Operator shall performed additional reclamation activities for this associated well location as well.