



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos
Location Name: Croaker #11-10
Location ID: 419495



Access road may have been pre-existing based on aerial imagery.



There is a livestock corral placed at the location.

Inspection Number: 694300073



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos
Location Name: Croaker #11-10
Location ID: 419495



There is vegetation establishment throughout the location which consists of Prairie threeawn, Sand dropseed, and Blue grama. The location is stabilized and there are no erosion issues.

There is a livestock corral placed at the locaion.

Inspection Number: 694300073