

Interim Reclamation and Stormwater Inspection

June 11, 2020

Operator: GREAT WESTERN OPERATING COMPANY LLC- #10110

Location ID: 446251

Inspection Document #: 697501626

Weld County, CO

SWSW Section 27 T1N R66W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: Rael /34-4-2HC
Location ID: 446251



Photo 1. Photo taken from the northwestern well location, facing Southeast. Photo illustrates Operator has performed interim reclamation activities.



Inspection Photos
Location Name: Rael /34-4-2HC
Location ID: 446251



Photo 2. Photo taken from the northwestern well location, facing East. See comments under Photo 1.



Inspection Photos
Location Name: Rael /34-4-2HC
Location ID: 446251



Photo 3. Photo taken from the northwestern well location, facing South. See comments under Photo 1.



Inspection Photos
Location Name: Rael /34-4-2HC
Location ID: 446251



Photo 4. Close up photo taken from the northwestern interim reclamation area. Photo illustrates the establishment of Russian thistle, which will have to be controlled and managed.





Photo 5. Close up photo taken from the western interim reclamation area. Photo illustrates the establishment of desirable species. However, Operator may need to perform additional reclamation activities as germination did not appear uniform.

Inspection Photos
Location Name: Rael /34-4-2HC
Location ID: 446251



Photo 6. Photo taken between the well location and facility location, facing South. Photo illustrates a List B Colorado noxious weed, Scotch thistle, alongside the access road and a portion of the flowline area.



Inspection Photos
Location Name: Rael /34-4-2HC
Location ID: 446251



Photo 7. Photo taken from the southern well location entrance, facing East. Photo illustrates a List B Colorado noxious weed, Scotch thistle.



Inspection Photos
Location Name: Rael /34-4-2HC
Location ID: 446251



Photo 8. Photo taken from the southern well location entrance, facing Southeast. Photo illustrates a List B Colorado noxious weed, Scotch thistle, along the southwestern location.

