

Inspection Photos  
Operator Name: GRIZZLY OPERATING LLC  
Location ID: 335440



Excavation area

Inspection Photos  
Operator Name: GRIZZLY OPERATING LLC  
Location ID: 335440



**Location and wells Locked out and tagged out**



**Flowlines removed and taken out of service, Flowlines from separator to tank battery**

Inspection Photos  
Operator Name: GRIZZLY OPERATING LLC  
Location ID: 335440



Target tee's showing external corrosion

Inspection Photos  
Operator Name: GRIZZLY OPERATING LLC  
Location ID: 335440



**Target tee's showing external corrosion**