

Inspection Photos

Loc#335912

Operator: Berry

Inspection Number: 692402309

Inspection Date: 6/11/20



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Photo#1:
Overview of Location to North.

June 11, 2020



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Berry Pet ALs Chevron L35 Loc#335912



Photo#2:
Overview of Location to South; and reference area.

June 11, 2020



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Berry Pet ALs Chevron L35 Loc#335912



Photo#3:
Close up of vegetation on location.

June 11, 2020



Photo#4:
Close up of vegetation on access road.



Photo#5:
Showing delineation of vegetation on perimeters of Location.

Photo#6:

June 11, 2020