

Inspection Photos  
Location Name: DuckClub Pad  
Location ID:456114



Photo#1 Location

Photo#2 Maintenance Tank and Separators

Inspection Photos  
Location Name: DuckClub Pad  
Location ID:456114



Photo#3 Gas Meter

Photo#4 Frac Tank

Inspection Photos  
Location Name: DuckClub Pad  
Location ID:456114



Photo#5 Wellhead

Photo#6 Wellhead

Inspection Photos  
Location Name: DuckClub Pad  
Location ID:456114




Photo#7 Wellhead

Photo#8 Wellhead

Inspection Photos  
Location Name: DuckClub Pad  
Location ID:456114



Photo#9 Wellhead



Photo#10 Wellhead

Inspection Photos  
Location Name: DuckClub Pad  
Location ID:456114



Photo#11 Wellhead



Photo#12 Wellhead

Inspection Photos  
Location Name: DuckClub Pad  
Location ID:456114



Photo#13 Wellhead

Photo#14 Wellhead

Inspection Photos  
Location Name: DuckClub Pad  
Location ID:456114



Photo#15 Wellhead

Photo#16 Wellhead