

Inspection Photos  
Location Name: Ocho Pad  
Location ID: 449174



Photo#1 Tank battery



Photo#2 ECDs/ECO Unit Recovery Unit

Inspection Photos  
Location Name: Ocho Pad  
Location ID: 449174



**Photo#4 Gas Meter/Buffer Tanks**

**Photo#5 VRUs**

**Inspection Photos**  
**Location Name: Ocho Pad**  
**Location ID: 449174**



**Photo#6 Compressor**



**Photo#7 Separators**


Inspection Photos  
Location Name: Ocho Pad  
Location ID: 449174



Photo#8 Wellhead

Photo#9 Wellhead

Inspection Photos  
Location Name: Ocho Pad  
Location ID: 449174



Photo#10 Wellhead

Photo#11 Wellhead

Inspection Photos  
Location Name: Ocho Pad  
Location ID: 449174



Photo#12 Wellhead



Photo#13 Wellhead

Inspection Photos  
Location Name: Ocho Pad  
Location ID: 449174



Photo#14 Wellhead/**Corrective Action Wellhead sign missing**

Photo#15 Wellhead

Inspection Photos  
Location Name: Ocho Pad  
Location ID: 449174



Photo#16 Wellhead



Photo#17 Wellhead

Inspection Photos  
Location Name: Ocho Pad  
Location ID: 449174



Photo#18 Wellhead

Photo#18 Wellhead

**Inspection Photos**  
**Location Name: Ocho Pad**  
**Location ID: 449174**



**Photo#18 Frac Tanks**