

**Inspection Photos**  
**Location Name: Horsetail 02D-0204**  
**Location ID: 437025**



**Photo 1 – Pumping Unit, Stained Soil at Wellhead**



**Photo 2 – Wellhead Sign**






**Inspection Photos**  
**Location Name: Horsetail 02D-0204**  
**Location ID: 437025**



**Photo 3 – Unused Tank**



**Photo 4 – Stained Soil at Exhaust**