

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:
06/15/2020
Submitted Date:
06/15/2020
Document Number:
699101946

FIELD INSPECTION FORM

Loc ID 323329 Inspector Name: Burns, Adam On-Site Inspection 2A Doc Num: _____

Operator Information:
OGCC Operator Number: 100322
Name of Operator: NOBLE ENERGY INC
Address: 1001 NOBLE ENERGY WAY
City: HOUSTON State: TX Zip: 77070

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

8 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
		NBL_DJBU_Inspections@NB LENERGY.COM	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
245075	WELL	SI	03/01/2020	OW	123-12870	DARLENE DINNEL 1	SI
418423	WELL	SI	11/01/2019	OW	123-31922	DINNEL C27-28D	SI

General Comment:

Location

Overall Good:

Signs/Marker:

Type	WELLHEAD		
Comment:	x2		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	Adequate	Date:	
Corrective Action:			

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type	WELLHEAD		
Comment:	Panel x2		
Corrective Action:		Date:	

Equipment:

Type: Bradenhead	# 2		corrective date
Comment:	Appear to be plumbed to surface		
Corrective Action:		Date:	
Type: Plunger Lift	# 2		
Comment:			
Corrective Action:		Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 245075 Type: WELL API Number: 123-12870 Status: SI Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment:

Corrective Action: Date: _____

Facility ID: 418423 Type: WELL API Number: 123-31922 Status: SI Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment:

Corrective Action: Date: _____

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary On Monday 6/15/20 at approximately 1120hrs, I, Inspector Adam Burns, Conducted an on-site inspection at Dinnel C27-28D & Darlene Dinnel 1 of Noble Energy at Location ID: 323329 in Weld County, Colorado. While there, I observed two wells that are SI, LO/TO. No violation of the COGCC rules were observed at the time of inspection. This is a summary of inspection report. Continuing education inspections</p>	burnsa	06/15/2020

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699101947	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5175077