

Inspection Photos

ALs Loc#336001

Operator: Berry

Inspection Number: 692402314

Inspection Date: 6/11/20



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Photo#1:
Overview of Location from Lease road, to South.

June 11, 2020



Photo#2:
Close up View of area vegetation.



Photo#3:
View of area vegetation.

June 11, 2020



Photo#4:

View of area vegetation; insert of Houndstongue; Operator, in Photo is holding armload of pulled Houndstongue.



Photo#5:

View of area vegetation to North and lease road.

June 11, 2020



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Berry Pet Chevron 12-4D ALS Loc#336001