

Inspection Photos

ALs Loc#335981

Operator: Berry

Inspection Number: 692402317

Inspection Date: 6/11/20



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Photo#1:
Overviews of vegetation establishment at Location.

June 11, 2020



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Berry Pet Chevron DO5 ALs Loc#335981



Photo#1:

View along South slope; insert shows close up ground view of new growth of Russian thistle emerging under desiccated growth

June 11, 2020



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Berry Pet Chevron DO5 ALs Loc#335981



Photo#3:
View of old growth Russian thistle in grass establishment.



Photo#4:
New growth of Russian thistle emerging under desiccated growth

June 11, 2020



Photo#5:
Noxious weed Houndstongue on site.

June 11, 2020