

Inspection Photos
Location Name: Neilson 3
API: 007-06116



Faded/illegible sign, unused equipment, weeds and combustible material (dead weeds)



Unused equipment (tank/barrel rack)

Inspection Photos
Location Name: Neilson 3
API: 007-06116



Crude oil running down side of tank

Inspection Photos
Location Name: Neilson 3
API: 007-06116



Weeds on and in containment berms, no anchoring or ring in floodplain

Inspection Photos
Location Name: Neilson 3
API: 007-06116



Weeds in berms, no anchoring or steel ring in floodplain



Weeds in berms, no anchoring in floodplain, south tank requiring paint

Inspection Photos
Location Name: Neilson 3
API: 007-06116



Oil stain, leaking valve north tank



Oily rags and debris