

Inspection Photos

ALs Loc#335842

Operator: Berry

Inspection Number: 692402319

Inspection Date: 6/11/20



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Photo#1:
Overviews of Location to Southwest.

June 11, 2020



Photo#1:

View along Southeast slope, showing sparse, patchy vegetation establishment.

June 11, 2020



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Berry Pet Latham Loc#335842



Photo#3:
Noxious weed Houndstongue on site.



Photo#4:
West side slope vegetation.

June 11, 2020