

Inspection Photos  
Location Name: Winter 29-D Pad  
Location ID: 433397



Photo 1: Wellhead Sign




Photo 2: Stained soil

**Inspection Photos**  
**Location Name: Winter 29-D Pad**  
**Location ID: 433397**




**Photo 3: Wellhead Sign**



**Photo 4: Stained soil**



**Inspection Photos**  
**Location Name: Winter 29-D Pad**  
**Location ID: 433397**



**Photo 5: Wellhead Sign**



**Photo 6: Stained soil**

Inspection Photos  
Location Name: Winter 29-D Pad  
Location ID: 433397



Photo 7: Wellhead Sign



Photo 8: Stained soil