

Inspection Photos

Location Name: CARPIO-66N64W /22NESE

Location #: 328190



Photo #1

Carpio 22-41 (05-123-15668) Wellsite

Plugged & Abandoned | PA

~ 15 yds.



Photo #2

Carpio 22-41 Battery site

Abandoned: *Most Equipment removed*

Inspection Photos

Location Name: CARPIO-66N64W /22NESE

Location #: 328190



Photo #3

Carpio 22-41 Battery site

Abandoned: Unused Equipment

Gas meter run / riser remains on site