




**Reference Number:** 20200529-18143734304  
**Form Name:** V2 Compliance Follow Up Form  
**Submitter Name:** Cole Nichols (colen@horizonenvservices.com) | colen@horizonenvservices.com  
**Submission Date:** May 29, 2020 10:15:08 AM MDT  
**Location:** 91 S Skylane Dr, Durango, CO 81303, USA  
 May 29, 2020 10:14:26 AM MDT [ [View Map](#) ]

## INFORMATION

### Section 1

**Name** colen@horizonenvservices.com  
**Date** May 28, 2020  
**Well Name** GEARHART GAS UNIT 01-32 FT 2  
**API Number** 50670867800  
**Select State** Colorado  
**Work type** COGCC Inspection AR  
**Action Complete** Other

### Photo of first corrective action completed



**Completed work description Corrective  
Action 1**

location sign

**Photo of second corrective action completed**



**Completed work description of corrective  
action 2**

treated noxious weeds

**Photo of third corrective action completed**



**Completed work description of corrective  
action 3**

treated noxious weeds

**Photo of fourth corrective action completed**



**Completed work description**

treated noxious weeds

**Completed work description of corrective action 4**

treated noxious weeds

**Additional photos**



**Additional photos**



**Completed work description**

treated noxious weeds in reclamation area and on pad

**Summary of all work completed**

previous treatment dates 7/15/16, 7/17/17, 7/10/18, 6/27/19